


# H TECHNICAL


## BULLETIN

### HT SERIES, INTRAAX TRAILER AIR SUSPENSION QUICK ALIGNMENT GUIDE CHANGE

No: TRAILER AUS - 014  
Subject: *Product Improvement*  
Date: February 1999 Revision: A



CURRENT VERSION  
Round alignment guide  
with full weld



NEW VERSION  
Two pieces of square  
steel stock

As part of our continuous product improvement program, Hendrickson has revised the alignment guide for the pivot bushing connection.

Changes will occur as followed;

- ? Intraax March
- ? HT250US March
- ? HT Series April

The current alignment, "eyebrow" design is being replaced with key stock material at the maximum alignment positions (10 and 2 o'clock). This new alignment guide reduces the possibility of the QUIK-ALIGN eccentric collar "riding up" on the guide due to improper collar installation.

This bulletin contains product improvement information only. Hendrickson is not committed or liable for canvassing existing product.

If any further installation detail or assistance is required, contact the Hendrickson Customer Excellence Centre on (03) 9767 3400.

**WARNING:**  
HENDRICKSON REMINDS USERS TO ADHERE TO THE PUBLISHED CAPACITY RATINGS FOR SUSPENSIONS.

DO NOT MODIFY PARTS OTHER THAN OUTLINED IN THIS PUBLICATION.

USE OF A MODIFIED OR SUBSTITUTE PART IS NOT RECOMMENDED BECAUSE THE PART MAY NOT MEET HENDRICKSON'S SPECIFICATIONS, WHICH COULD LEAD TO FAILURE OF THE PART, LOSS OF VEHICLE CONTROL AND PERSONAL INJURY.