

TECHNICAL BULLETIN

ALL TRUCK & TRAILER AIR SUSPENSIONS

No: 97117-103
Subject: *Service CD*
Date: Jan 2004

Revision: B



Previous Version



Current Version

As part of our continuous product improvement program, Hendrickson wish to advise Authorised Repairers that the Service & Product CD has been updated .

PARTS & SERVICE CD

Hendrickson Asia Pacific has reissued and updated CD (97117-100 Rev B) to replace the previous Service & Product CD (97117-100 Rev A) This is available to all Authorised Hendrickson Repairers.

MINIMUM REQUIRMENTS

Windows 95, Acrobat Reader, Internet Explorer and Microsoft Office.

PROCEDURE

The CD is Web based and can be run directly from the disc or for faster performance transfer the contents to your hard drive.

1. The disc should start automatically on most operating systems should it not open automatically, double click on the "Home" icon to start the program.
2. To enter the Service & Product Section select the "Reference Icon.
3. Enter your password and Click on the [H] Icon, this will take you to the Manual.
4. Select the required topic from the side index and use the back arrow to exit that particular section.
5. If further assistance is required, contact the Hendrickson Product Support Department on 03 9767 3400 or technicalservice@hendrickson.com.au